


How to install the cutting die of coin cell disc cutter AOT-CP60?




Different dies for cutting electrode and battery separator:




Website :www.aotbattery.com Email: sales@aotbattery.com Tel :(+86)-592-7161550 Address: No.168, Zhaogang Road, Xiang'an District, Xiamen City, China



Step1: Install upper die, and fasten it with screw.



Step2: Take off the rubber which is on the upper die.




Website :<u>www.aotbattery.com</u> Email: <u>sales@aotbattery.com</u> Tel :(+86)-592-7161550 Address: No.168, Zhaogang Road, Xiang'an District, Xiamen City, China



Step 3: Match the upper die and lower die, make them closed in a good condition.




Step 4: Press the handle and hold on, make sure the holes are aligned.



Website :<u>www.aotbattery.com</u> Email: <u>sales@aotbattery.com</u> Tel :(+86)-592-7161550 Address: No.168, Zhaogang Road, Xiang'an District, Xiamen City, China



Step 5: Fit and fasten the screws by the wrench, and then loosen the handle.



Step 6: Put on the rubber, then you can start cutting battery electrode



Website :<u>www.aotbattery.com</u> Email: <u>sales@aotbattery.com</u> Tel :(+86)-592-7161550 Address: No.168, Zhaogang Road, Xiang'an District, Xiamen City, China